



# Leak Detection and Repair (LDAR) Annual Report Form

(Version December 18, 2014)  
Regulation 7, Section XVII.F.9

## Section 1: General Information

Company Name:	Augustus Energy Partners, LLC		
Inspection Year:	2015	# Facilities Inspected: <sup>1</sup>	9
Contact Person:	Duane Zimmerman	Title:	Vice President of Operations
Phone Number:	(406)294-5990	E-mail Address:	dzimmerman@augustusenergy.com

<sup>1</sup> Identify the list of facilities inspected in the Addendum Table 1 in Section 5

## Section 2: LDAR Inspections

Inspection Method	# Inspections
AIMM at Natural Gas Compressor Stations:	9
AIMM at Well Production Facilities:	N/A
AVO at Well Production Facilities:	N/A
<b>TOTAL</b>	<b>9</b>

## Section 3: Leaking Components Details

Component Type	# Leaks Identified	# Leaks Repaired	# Leaks on Delay of Repair List as of Dec 31
Valves:	2	2	0
Connectors:	11	11	0
Flanges:	1	1	0
Pump Seals:	0	0	0
Pressure Relief Devices:	1	1	0
<b>TOTAL</b>	<b>15</b>	<b>15</b>	<b>0</b>

## Section 4: Responsible Official Certification

All information contained in the LDAR Annual Report must be certified by a responsible official as defined in Colorado Regulation No. 3, Part A, Section 1.B.38.

Please note the Colorado Statutes state that any person who knowingly, as defined in §18-1-501(6), C.R.S., makes any false material statement, representation, or certification in this document is guilty of a misdemeanor and may be punished in accordance with the provisions of §25-7 122.1, C.R.S.

I, the Responsible Official, have reviewed this annual report in its entirety and, based on information and belief formed after reasonable inquiry, I certify that the statements and information contained in this report are true, accurate and complete.

Printed/Typed Name - Responsible Official:	Title:
Duane Zimmerman	Vice President of Operations
Signature:	Date:
	11/17/2015

