

Forest View Acres Water District

Operations Report – September, 2010

Prepared by Erik Tamerler, Southwest Water Co.

Sampling:

- The required samples were collected for Routine Coliform. Received results are inside the yellow folder in the Arapahoe treatment plant.

Treatment Plants:

Arapahoe Water Plant:

- Has been operating normally.
- Well level readings are still low during operation.

Transmission Line/Booster Station:

- Normal Operation.
- Construction of the new line has been started.

Surface Water Plant:

- The plant is being run at a reduced flow of 30-40gpm. The creek is very low.
- A lens on one of the secondary filters is cracked and must be replaced. New lenses are on hand. The secondary filters will also be raked at that time.

Distribution system:

- There is a small leak near the south end of Granite Cir. We will have this repaired at a later date.

Miscellaneous: