Valve Exercising

10/7/2013

GREATROCK NORTH
Subdivision

Page Number	Number of Valves Exercised	Valves Not Able To Exercise
1	4	0
2	2	0
3	4	0
4	4	0
5	3	0
6	4	0
7	3	0
8	4	0
9	3	0
10	7	0
11	2	0
12	4	1
13	2	0
14	2	0
15	2	0
16	1	0
17	1	0
18	0	0
Total	**52**	**1**

Problems

Page Number		
GN	2	Valve Not On Map
GN	11	Broken Top Section
GN	11	Wrong Type Lid
GN	12	No Hydrant Valve (under asphalt?)
GN	16	Broken Top Section

Total Valves **53**

Valve Exercising

10/7/2013

ROCKING HORSE FARM
Subdivision

Page Number	Number of Valves Exercised	Valves Not Able To Exercise
1	3	1
2	1	0
3	4	0
4	5	0
5	7	0
6	4	0
7	9	0
8	3	0
9	3	1
10	1	0
11	1	0
12	1	0
13	7	0
14	1	0
15	1	0
16	2	0
17	2	0
18	1	0
Total	**56**	**2**

Problems

Page Number	
RHF 1	No Hydrant Valve
RHF 2	North Arrow Wrong Direction
RHF 4	Hard to Operate
RHF 7	Mapping Wrong (see # 16)
RHF 7	North Arrow Wrong Direction
RHF 8	Hydrant Hit by Vehicle (Loose in Ground)
RHF 9	Valve Not on Map
RHF 9	No Hydrant Valve
RHF 12	Valve was found closed (Left Open)

Total Valves **58**

Valve Exercising

10/7/2013

BOX ELDER CREEK RANCH
Subdivision

Page Number	Number of Valves Exercised	Valves Not Able To Exercise
1	2	0
2	5	0
3	6	0
4	1	0
5	4	0
6	3	0
7	5	0
8	2	0
9	6	0
10	5	0
11	1	0
12	1	0
13	4	0
14	4	0
15	4	0
16	1	0
17	1	1
18	1	0
19	2	0
20	2	0
21	9	0
22	1	0
23	2	0
24	5	0
25	3	0
26	6	0
27	6	0
28	0	0
29	4	0
30	1	0
31	1	0
32	0	0
Total	**98**	**1**

Problems

Page Number	
BE 3	Hard to Operate
BE 5	Two Valves not on Map
BE 8	Two Line Valves (Not Blow Off)
BE 12	Valves not on Map
BE 17	No Hydrant Valve (under asphalt?)
BE 26	No Line Valve to North
BE 27	Line Valve, to North, Not on Map

Total Valves **99**