Ramey Environmental Compliance, Inc.
Equipment Services Division (ESD)
PO Box 99, Firestone, CO 80520
Office: 303-833-5505
Fax: 303-833-5535

Estimate: ESD-1101

DATE: 8/20/2014

NAME / ADDRESS
Greatrock North Water & Sanitation Dist c/o Special District Management Services Attn: Lisa Johnson- Dist. Mgr 141 Union Blvd, Suite 150 Lakewood, CO 80228

Estimated Delivery Time: TBD

Terms:

Note: All applicable Freight Charges, Taxes and Permit Fees will be added.

Customer PO No.:	PENDING

*****ESTIMATE IS VALID FOR 30 DAYS*****

EQUIPMENT SERVICES DIVISION (ESD) PROJECT

DESCRIPTION	QTY	COST	TOTAL
Box Elder Fire Pump Leaks			
-1/2" Union Drip Leak at PRV -Drip Leak at Isolation Valve East of the Fire Pump PRV			
Field Labor to repair the above leaks (Includes first visit to inspect issues)	4	95.00	380.00
Parts necessary to repair leaks:	1	243.28	243.28
- (3") SCH80 PVC Pipe - (3") SCH80 PVC Van Stone Flange - (3") SCH80 PVC Union - (1") Brass Union - (1/2") Brass Close Nipples - (1/2") Brass Cross Fitting			

Please let us know if you any questions. Thank you!	***TOTAL:***	**$623.28**

If this estimate is acceptable, please sign and return by fax to (303)833-5535.

_____	_____
Authorized Signature	**Date**