



Forest View Acres Water District

Operations Report – October, 2010

Prepared by Brenda Smith, SouthWest Water Company.

Sampling:

- The required sample was collected for the Routine Coliform.
 - The required Lead and Copper samples were collected.
- Received results received are within normal range and are on site inside the yellow folder in the Arapahoe treatment plant.

Treatment Plants:

Arapahoe Water Plant:

- Has been operating normally.
- Well level readings are getting better/ higher during operation.

Transmission Line/Booster Station:

- Normal Operation, a new T was installed to feed temporary tanks, temporary tanks are being installed. The road to the tank has been cleared.
- Construction of the new line has been started and is up to Red Rock Ranch Drive and Stone View Road, the distribution line has been hit 6 times since the project started due to it's real unknown location.
- The Booster Station's modification has been completed, it just needs to be fine tuned and a small part on a Cla-Valve repaired.

Surface Water Plant:

- The plant is being run at a reduced flow of 30-40gpm and is running above any expectations even thou the creek is very low.
- A lens on one of the secondary filters was replaced and the filter was raked.
- The air compressor was repaired with a new switch.
- The Inlet was cleaned.

Distribution system:

- The small leak near the south end of Granite Circle was repaired.
- The line leak connected to the Fire Hydrant at Sierra Vista and Pike View Way was repaired.

Miscellaneous:

- Address 18450 Pixie Park Road was inspected for water usage before meter, none was found.
- 3 meters in the District quit working, one of the three has been changed out one is being scheduled and the third will be pink tag posted again.
- The bears are swimming in the back wash pond
- RG has been on site and has been so helpful.

Thank you,

Brenda Smith
SouthWest Water Company