

## **Forest View Acres Water District**

Operations Report –August/September 2011  
....Prepared by Gabrielle Begeman  
ORC LLC

### **Treatment Plants:**

#### Arapahoe Water Plant:

- The production out of the well has decreased slightly to an average 90 GPM down from 95 GPM last month.
- With the automatic nature of the AWP operation, we cannot obtain readings of the depth of water over the well pump consistently before, during or after a run. However, with the limited readings we have, we can see that adequate recharge is happening.
- I suggest installing a transducer that can provide a constant readout of the depth of water over the pump when we rehab the well. This will provide us with a better insight of our water availability.

#### Surface Water Plant:

- We have had a number of plant shut downs due to the air compressor tripping the breaker. The auto dialer is not currently configured to call out and alert us of a shut down. This has decreased our overall production from the SWTP for the month.
- For the month of August we have been lucky to be able to get 20 GPM out of the canyon, and more often are fluctuating from 12-18 GPM.

### **Distribution system**

#### Leaks

- We had 1 leak in the driveway of 18855 Rock Brook that was fixed by J&K on 8/29.
- Please see the email correspondence RE the sewer line issue for 18704 Rock Brook Rd.

#### Production Report

- I have been working with Sandy and Joel on the numbers for billed vs produced.

#### Meter Pit Specs

- Brenda and I have begun to revise the meter pit specs. A copy for the boards review should be available by the board meeting in October.

#### Master Meters

- Meter pits and meters are in the works. See attached schedule.