



410 17th Street, Suite 1500
Denver, CO 80202
(720) 440-6100 phone
(720) 305-0804 fax

Bonanzacrk.com

May 25, 2016

Colorado Department of Public Health and Environment
Air Pollution Control Division
APCD-SS-B1
4300 Cherry Creek Drive South
Denver, Colorado 80246-1530

**RE: Bonanza Creek Energy Operating Company, LLC
LDAR Annual Report
Regulation 7, XVII.F.9**

To Whom it may concern,

Bonanza Creek Energy Operating Company, LLC (BCEOC) is submitting this annual report as required under Regulation 7, XVII.F.9. Included with this letter is the requisite Annual Report Form that lists all of the LDAR inspections (Reg. 7 XVII.F) performed at facilities during 2015. The leaks identified and subsequently repaired at inspected facilities during this reporting period are identified in Section 3 on the attached and as required under Section XVII.F.9.c-d.

The signed Responsible Official Certification, as required under Section XVII.F.9.f, is also included in Section 4 of the attached Annual Report Form. If you have questions or need additional information please contact me John Gardner at 303-803-1717.

Sincerely,

A handwritten signature in black ink, appearing to read 'John Gardner', is written over a light blue horizontal line.

John Gardner
Senior Environmental Specialist

Attachments: As stated

cc: File

Leak Detection and Repair (LDAR) Annual Report Form¹



Please submit via email to: cdphe_reg7LDAR_annualreports@state.co.us

Section 1: General Information

Company Name:	Bonanza Creek Energy Operating Company, LLC		
Inspection Year:	2015	# Facilities Inspected: ²	260
Contact Person:	John Gardner	Title:	Sr. Environmental Specialist
Phone Number:	303-803-1717	E-mail Address:	jgardner2@bonanzacrk.com

Section 2: LDAR Inspections

Inspection Method	# Inspections ³
AIMM at Natural Gas Compressor Stations:	9
AIMM at Well Production Facilities:	1055
AVO at Well Production Facilities:	644
TOTAL	

Section 3: Leaking Components Details

Component Type	# Leaks Identified ⁴	# Leaks Repaired	# Leaks on Delay of Repair List as of Dec 31
Valves:	106	106	0
Connectors:	199	197	2
Flanges:	24	24	0
Pump Seals:	1	1	0
Pressure Relief Devices:	25	25	0
TOTAL	355	353	2

Section 4: Responsible Official Certification

All information contained in the LDAR Annual Report must be certified by a responsible official as defined in Colorado Regulation No. 3, Part A, Section 1.B.38.

Please note the Colorado Statutes state that any person who knowingly, as defined in §18-1-501(6), C.R.S., makes any false material statement, representation, or certification in this document is guilty of a misdemeanor and may be punished in accordance with the provisions of §25-7 122.1, C.R.S.

I, the Responsible Official, have reviewed this annual report in its entirety and, based on information and belief formed after reasonable inquiry, I certify that the statements and information contained in this report are true, accurate and complete.

Printed/Typed Name - Responsible Official:	Title:
Dean Tinsley	VP, Rocky Mountain Asset Management
Signature:	Date:
	5/24/2016

