



**Meadowlark Midstream Company, LLC**  
999 18<sup>th</sup> Street, Suite 3400 South  
Denver, CO 80202  
Phone: 720.452.6225  
[www.summitmidstream.com](http://www.summitmidstream.com)

May 19, 2017

Colorado Department of Public Health and Environment  
Air Pollution Control Division  
4300 Cherry Creek Drive South  
Denver, CO 80246-1530

**RE: Regulation 7 Annual LDAR Report  
Meadowlark Midstream Company, LLC**

Dear Sir / Madam,

Summit Midstream Partners, LLC, on behalf of Meadowlark Midstream Company, LLC would like to submit the annual LDAR report for the period of January 1, 2016 to December 31, 2016 for the Angus Compressor Station located in Weld County, Colorado. The report is being submitted in accordance with the LDAR reporting requirements contained in Regulation 7, XVII.F.9.

If you need any other information, please contact me either by telephone or email. If you should have any specific questions related to this submittal, please contact EJ Lachendro with Summit Midstream Partners, LLC at (720) 441-0241 or [elachendro@summitmidstream.com](mailto:elachendro@summitmidstream.com).

Sincerely,

Zak N. Covar  
Vice President of HSE&R  
Summit Midstream Partners, LLC  
Office: (832) 608-6175  
[zcovar@summitmidstream.com](mailto:zcovar@summitmidstream.com)

# Leak Detection and Repair (LDAR) Annual Report Form<sup>1</sup>



Please submit via email to: [cdphe\\_reg7LDAR\\_annualreports@state.co.us](mailto:cdphe_reg7LDAR_annualreports@state.co.us)

## Section 1: General Information

Company Name:	Meadowlark Midstream Company, LLC		
Inspection Year:	2016	# Facilities Inspected: <sup>2</sup>	1
Contact Person:	EJ Lachendro	Title:	Environmental Compliance Specialist
Phone Number:	720-441-0241	E-mail Address:	<a href="mailto:elachendro@summitmidstream.com">elachendro@summitmidstream.com</a>

## Section 2: LDAR Inspections

Inspection Method	# Inspections <sup>3</sup>
AIMM at Natural Gas Compressor Stations:	1
AIMM at Well Production Facilities:	NA
AVO at Well Production Facilities:	NA
<b>TOTAL</b>	<b>1</b>

## Section 3: Leaking Components Details

Component Type	# Leaks Identified <sup>4</sup>	# Leaks Repaired	# Leaks on Delay of Repair List as of Dec 31
Valves:	0	0	0
Connectors:	0	0	0
Flanges:	0	0	0
Pump Seals:	0	0	0
Pressure Relief Devices:	0	0	0
<b>TOTAL</b>	<b>0</b>	<b>0</b>	<b>0</b>

## Section 4: Responsible Official Certification

All information contained in the LDAR Annual Report must be certified by a responsible official as defined in Colorado Regulation No. 3, Part A, Section 1.B.38.

Please note the Colorado Statutes state that any person who knowingly, as defined in §18-1-501(6), C.R.S., makes any false material statement, representation, or certification in this document is guilty of a misdemeanor and may be punished in accordance with the provisions of §25-7 122.1, C.R.S.

I, the Responsible Official, have reviewed this annual report in its entirety and, based on information and belief formed after reasonable inquiry, I certify that the statements and information contained in this report are true, accurate and complete.

Printed/Typed Name - Responsible Official:	Title: VP-Health, Safety, Environmental, & Regulatory
Zak N. Covar	Vice President of HSE&R
Signature: 	Date: May-22-2017

