



March 23, 2016

Delivered Via Email to: cdphe_reg7LDAR_annualreports@state.co.us

Colorado Department of Health and Environment
Air Pollution Control Division
4300 Cherry Creek Drive South
Denver, CO 80246

Re: *Condor Energy Technology, LLC
Leak Detection and Repair Annual Report
Weld & Morgan Counties, Colorado*

To whom it may concern,

Please find enclosed the Leak Detection and Repair Annual Report for the reporting year 2015. Please note that Condor Energy Technology, LLC operates five (5) facilities in Weld and Morgan Counties in Colorado. Five (5) LDAR inspections were completed at those facilities along with thirty five (35) AVO inspections throughout the facilities. Please feel free to contact the representative below if you have any questions or concerns.

Please do not hesitate to contact our representatives:

Angie Galvan, Regulatory Analyst:
Office Phone: 281-716-5730
Business Hours: 9 AM – 5 PM Central Time Monday through Friday
Email: Angie.Galvan@stxra.com

Sincerely,

A handwritten signature in black ink that reads "Yiyang Zhang". The signature is fluid and cursive, with a long horizontal stroke extending to the right.

Yiyang (Dave) Zhang, Manager
Condor Energy Technology, LLC

Enclosures: LDAR 2015 Annual Report Form
cc: file

Leak Detection and Repair (LDAR) Annual Report Form¹



Please submit via email to: cdphe_reg7LDAR_annualreports@state.co.us

Section 1: General Information

Company Name:	Condor Energy Technology, LLC		
Inspection Year:	2015	# Facilities Inspected: ²	5
Contact Person:	Angie Galvan	Title:	Regulatory Analyst
Phone Number:	281-716-5730 ex. 0	E-mail Address:	angie.galvan@stxra.com

Section 2: LDAR Inspections

Inspection Method	# Inspections ³
AIMM at Natural Gas Compressor Stations:	
AIMM at Well Production Facilities:	5
AVO at Well Production Facilities:	35
TOTAL	40

Section 3: Leaking Components Details

Component Type	# Leaks Identified ⁴	# Leaks Repaired	# Leaks on Delay of Repair List as of Dec 31
Valves:	9	9	0
Connectors:	4	4	0
Flanges:	0	0	0
Pump Seals:	0	0	0
Pressure Relief Devices:	0	0	0
TOTAL	13	13	0

Section 4: Responsible Official Certification

All information contained in the LDAR Annual Report must be certified by a responsible official as defined in Colorado Regulation No. 3, Part A, Section 1.B.38.

Please note the Colorado Statutes state that any person who knowingly, as defined in §18-1-501(6), C.R.S., makes any false material statement, representation, or certification in this document is guilty of a misdemeanor and may be punished in accordance with the provisions of §25-7 122.1, C.R.S.

I, the Responsible Official, have reviewed this annual report in its entirety and, based on information and belief formed after reasonable inquiry, I certify that the statements and information contained in this report are true, accurate and complete.

Printed/Typed Name - Responsible Official:	Title:
Yiyang (Dave) Zhang	Manager
Signature:	Date:
	04/29/2016

