



880 Wolverine Court  
Castle Rock, CO 80108  
Phone: 303-489-8773

# CP Exploration



April 11, 2016

Mr. Mark McMillan  
Colorado Department of Public Health and Environment  
Air Pollution Control Division APCD-SS-B1  
4300 Cherry Creek Drive South  
Denver, CO 80246

**RE: CP EXPLORATION II, LLC – REGULATION 7 LDAR 2015 ANNUAL REPORT**

Dear Mr. McMillan,

Please find enclosed the annual Leak Detection and Repair (LDAR) report for the facilities listed below. The report uses the Colorado Department of Public Health and Environment LDAR Annual Report Form to comply with Regulation 7, Section XVII.F.9.

- Teepee Park Ranch (TPR) 25-A If you have any questions or concerns please do not hesitate to contact me at 303-489-8773 or [wgiltner@cpxoil.com](mailto:wgiltner@cpxoil.com).

Respectfully,

Ward Giltner  
General Manager  
CP Exploration II, LLC

# Leak Detection and Repair (LDAR) Annual Report Form<sup>1</sup>



Please submit via email to: [cdphe\\_reg7LDAR\\_annualreports@state.co.us](mailto:cdphe_reg7LDAR_annualreports@state.co.us)

## Section 1: General Information

Company Name:	CP Exploration II, LLC		
Inspection Year:	2015	# Facilities Inspected: <sup>2</sup>	1
Contact Person:	Ward Giltner	Title:	General Manager
Phone Number:	303-489-8773	E-mail Address:	<a href="mailto:wgiltner@cpxoil.com">wgiltner@cpxoil.com</a>

## Section 2: LDAR Inspections

Inspection Method	# Inspections <sup>3</sup>
AIMM at Natural Gas Compressor Stations:	0
AIMM at Well Production Facilities:	1
AVO at Well Production Facilities:	0
<b>TOTAL</b>	<b>1</b>

## Section 3: Leaking Components Details

Component Type	# Leaks Identified <sup>4</sup>	# Leaks Repaired	# Leaks on Delay of Repair List as of Dec 31
Valves:	0		
Connectors:	0		
Flanges:	0		
Pump Seals:	0		
Pressure Relief Devices:	0		
<b>TOTAL</b>	<b>0</b>	<b>0</b>	<b>0</b>

## Section 4: Responsible Official Certification

All information contained in the LDAR Annual Report must be certified by a responsible official as defined in Colorado Regulation No. 3, Part A, Section 1.B.38.

Please note the Colorado Statutes state that any person who knowingly, as defined in §18-1-501(6), C.R.S., makes any false material statement, representation, or certification in this document is guilty of a misdemeanor and may be punished in accordance with the provisions of §25-7 122.1, C.R.S.

I, the Responsible Official, have reviewed this annual report in its entirety and, based on information and belief formed after reasonable inquiry, I certify that the statements and information contained in this report are true, accurate and complete.

Printed/Typed Name - Responsible Official:	Title:
Ward Giltner	General Manager
Signature:	Date: 4/11/2016



CP Exploration

**AIMM Inspection Form**

Section 1.0 – Site Information

Facility Name:	TPR 25-A	Facility AIRS ID:	
Name of Inspector:	Reed Wold	Date of Inspection:	12/22/15

Section 2.0 – Site Inspections

Section 2.1 – AIMM Inspection

Section 2.2.1 – General AIMM Inspection Information

Inspection Designation:	<input checked="" type="radio"/> Initial Inspection	<input type="radio"/> Periodic Inspection
Inspection Method Used:	IR Camera	If Other Please Describe:

Section 2.2.3 – Summary of Leaking Components

Table 3: Summary of Leaking Components	
Component Type	Number of Leaks
Valves:	0
Connectors:	0
Flanges:	0
Pump Seals:	0
Pressure Relief Devices:	0
Other Components:	0
<b>TOTAL</b>	

Section 2.2.4 – Corrective Actions

Yes	No	
<input type="radio"/>	<input checked="" type="radio"/>	Are there any new corrective actions (leaks) associated with this inspection?

Section 2.2.5 – Additional Comments

