

Leak Detection and Repair (LDAR) Annual Report Form¹



Please submit via email to: cdphe_reg7LDAR_annualreports@state.co.us

Section 1: General Information

Company Name:	Iron Horse Resources, Inc.		
Inspection Year:	2015	# Facilities Inspected: ²	11
Contact Person:	Mark McNamee	Title:	Operations Manager
Phone Number:	303-898-0989	E-mail Address:	mark@windmillenergy.net

Section 2: LDAR Inspections

Inspection Method	# Inspections ³
AIMM at Natural Gas Compressor Stations:	0
AIMM at Well Production Facilities:	11
AVO at Well Production Facilities:	0
TOTAL	11

Section 3: Leaking Components Details

Component Type	# Leaks Identified ⁴	# Leaks Repaired	# Leaks on Delay of Repair List as of Dec 31
Valves:	0		
Connectors:	0		
Flanges:	0		
Pump Seals:	0		
Pressure Relief Devices:	2	2	0
TOTAL	2	2	0

Section 4: Responsible Official Certification

All information contained in the LDAR Annual Report must be certified by a responsible official as defined in Colorado Regulation No. 3, Part A, Section 1.B.38.

Please note the Colorado Statutes state that any person who knowingly, as defined in §18-1-501(6), C.R.S., makes any false material statement, representation, or certification in this document is guilty of a misdemeanor and may be punished in accordance with the provisions of §25-7 122.1, C.R.S.

I, the Responsible Official, have reviewed this annual report in its entirety and, based on information and belief formed after reasonable inquiry, I certify that the statements and information contained in this report are true, accurate and complete.

Printed/Typed Name - Responsible Official:	Title:
Mark McNamee	Operations Manager
Signature:	Date:
	2/12/16

