

Leak Detection and Repair (LDAR) Annual Report Form¹



Please submit via email to: cdphe_reg7LDAR_annualreports@state.co.us

Section 1: General Information

Company Name:	Renegade Oil & Gas Company, LLC		
Inspection Year:	2015	# Facilities Inspected: ²	171
Contact Person:	J.B. Condill	Title:	CFO/VP-Land
Phone Number:	303 680-4725	E-mail Address:	jbcrog@aol.com

Section 2: LDAR Inspections

Inspection Method	# Inspections ³
AIMM at Natural Gas Compressor Stations:	0
AIMM at Well Production Facilities:	171
AVO at Well Production Facilities:	1152
TOTAL	1323

Section 3: Leaking Components Details

Component Type	# Leaks Identified ⁴	# Leaks Repaired	# Leaks on Delay of Repair List as of Dec 31
Valves:	26	4	22
Connectors:	8	2	6
Flanges:	12	0	12
Pump Seals:	0	0	0
Pressure Relief Devices:	4	0	4
TOTAL	50	6	44

Section 4: Responsible Official Certification

All information contained in the LDAR Annual Report must be certified by a responsible official as defined in Colorado Regulation No. 3, Part A, Section 1.B.38.

Please note the Colorado Statutes state that any person who knowingly, as defined in §18-1-501(6), C.R.S., makes any false material statement, representation, or certification in this document is guilty of a misdemeanor and may be punished in accordance with the provisions of §25-7 122.1, C.R.S.

I, the Responsible Official, have reviewed this annual report in its entirety and, based on information and belief formed after reasonable inquiry, I certify that the statements and information contained in this report are true, accurate and complete.

Printed/Typed Name - Responsible Official:	Title:
J.B. Condill	CFO/VP-Land
Signature:	Date:
	08/23/2016

