



May 27, 2016

Colorado Department of Public Health and Environment
Air Pollution Control Division, APCD-SS-B1
4300 Cherry Creek Drive South
Denver, CO 80246-1530

Subject: 2015 Annual Leak Detection and Repair (LDAR) Report
St. Croix Operating Inc.
P.O. Box 13799
Denver, Colorado 80403

To Whom It May Concern:

On behalf of St. Croix Operating Inc. (St. Croix), CGRS Inc. herein submits the 2015 Annual Leak Detection and Repair (LDAR) Report as required by Colorado Regulation 7, Section XVII.F.9. Included with this letter is the requisite Annual Report Form, quantifying the LDAR inspections performed at facilities that were subject to Regulation 7, Section XVII.F in 2015.

Please note that the attached report reflects more AVO inspections than were required by Regulation 7, Section XVII.F. St. Croix has been proactive with their LDAR program by implementing regular AVO inspections prior to the required LDAR phase-in schedule, as a best management practice.

If you have any questions or concerns regarding the attached 2015 Annual LDAR Report, please call me or Mr. Ken Rogowski at (800) 288-2657.

Sincerely,
CGRS, Inc.

Ken Rogowski
Project Manager

2015 Annual Leak Detection and Repair (LDAR) Report
St. Croix Operating Inc.
P.O Box 13799
Denver, CO 80403



Attachments:

2015 CDPHE Annual Leak Detection and Repair (LDAR) Report Form

Ec: Mr. Paul Melnychenko; stcroixexp@aol.com

Leak Detection and Repair (LDAR) Annual Report Form¹



Please submit via email to: cdphe_reg7LDAR_annualreports@state.co.us

Section 1: General Information

Company Name:	St. Croix Operating, Inc.		
Inspection Year:	2015	# Facilities Inspected: ²	2
Contact Person:	Paul Melnychenko	Title:	President
Phone Number:	303-595-4597	E-mail Address:	stcroix@aol.com

Section 2: LDAR Inspections

Inspection Method	# Inspections ³
AIMM at Natural Gas Compressor Stations:	N/A
AIMM at Well Production Facilities:	6
AVO at Well Production Facilities:	24
TOTAL	30

Section 3: Leaking Components Details

Component Type	# Leaks Identified ⁴	# Leaks Repaired	# Leaks on Delay of Repair List as of Dec 31
Valves:	0	0	0
Connectors:	0	0	0
Flanges:	0	0	0
Pump Seals:	0	0	0
Pressure Relief Devices:	0	0	0
TOTAL	0	0	0

Section 4: Responsible Official Certification

All information contained in the LDAR Annual Report must be certified by a responsible official as defined in Colorado Regulation No. 3, Part A, Section 1.B.38.

Please note the Colorado Statutes state that any person who knowingly, as defined in §18-1-501(6), C.R.S., makes any false material statement, representation, or certification in this document is guilty of a misdemeanor and may be punished in accordance with the provisions of §25-7 122.1, C.R.S.

I, the Responsible Official, have reviewed this annual report in its entirety and, based on information and belief formed after reasonable inquiry, I certify that the statements and information contained in this report are true, accurate and complete.

Printed/Typed Name - Responsible Official:	Title:
Paul Melnychenko	President
Signature:	Date:
	May 27, 2016

