



1001 Noble Energy Way  
Houston, Texas 77070  
281.872.3100

May 23, 2016

Mr. Christopher Laplante  
Air Pollution Control Division  
Colorado Department of Public Health and Environment  
APCD-SS-B1  
4300 Cherry Creek Drive South  
Denver, CO 80246

**SUBJECT: Transmittal of Noble Midstream Services, LLC's 2015 LDAR Report**

Dear Mr. Laplante:

Attached is the 2015 annual report summarizing COLORADO RIVER DEVCO LP's leak detection and repair activities conducted during the 2015 calendar year. This report is due to the Division by May 31, 2016 as required by Regulation 7, §XVII.F.9.

- An estimated 275,000 components were inspected in 2015 with a component leak rate of only 0.02%
- Facility received over 200 audio, visual, olfactory (AVO) and IR camera inspections in 2015
- There were no leaks on the delayed repair list on December 31, 2015

Please contact me at (303) 228-4196 if you have any questions.

Sincerely,

A handwritten signature in red ink, appearing to read 'Sarah K. Koziolkowsky'.

Sarah Koziolkowsky  
Environmental Scientist

COLORADO RIVER DEVCO LP

By: Colorado River DevCo GP LLC, its general partner

By: Noble Midstream Services, LLC, its sole member

cc: Brian Taylor, COLORADO RIVER DEVCO LP  
Phil Schlagel, COLORADO RIVER DEVCO LP  
Don Baskin, COLORADO RIVER DEVCO LP

# Leak Detection and Repair (LDAR) Annual Report Form<sup>1</sup>



Please submit via email to: [cdphe\\_reg7LDAR\\_annualreports@state.co.us](mailto:cdphe_reg7LDAR_annualreports@state.co.us)

## Section 1: General Information

Company Name:	COLORADO RIVER DEVCO LP		
Inspection Year:	2015	# Facilities Inspected: <sup>2</sup>	1
Contact Person:	Sarah Koziolkowsky	Title:	Environmental Scientist
Phone Number:	303-228-4196	E-mail Address:	<a href="mailto:s.koziolkowsky@nblenergy.com">s.koziolkowsky@nblenergy.com</a>

## Section 2: LDAR Inspections

Inspection Method	# Inspections <sup>3</sup>
AIMM at Natural Gas Compressor Stations:	0
AIMM at Well Production Facilities:	12
AVO at Well Production Facilities:	211
<b>TOTAL</b>	<b>223</b>

## Section 3: Leaking Components Details

Component Type	# Leaks Identified <sup>4</sup>	# Leaks Repaired	# Leaks on Delay of Repair List as of Dec 31
Valves:	25	25	0
Connectors:	6	6	0
Flanges:	5	5	0
Pump Seals:	3	3	0
Pressure Relief Devices:	12	12	0
<b>TOTAL</b>	<b>51</b>	<b>51</b>	<b>0</b>

## Section 4: Responsible Official Certification

All information contained in the LDAR Annual Report must be certified by a responsible official as defined in Colorado Regulation No. 3, Part A, Section 1.B.38.

Please note the Colorado Statutes state that any person who knowingly, as defined in §18-1-501(6), C.R.S., makes any false material statement, representation, or certification in this document is guilty of a misdemeanor and may be punished in accordance with the provisions of §25-7 122.1, C.R.S.

I, the Responsible Official, have reviewed this annual report in its entirety and, based on information and belief formed after reasonable inquiry, I certify that the statements and information contained in this report are true, accurate and complete.

Printed/Typed Name - Responsible Official:	Title:
<i>John Nicholson</i>	COO
Signature:	Date:
<i>John Nicholson</i>	5-27-16

