

PO Box 494  
Akron, CO 80720

April 1, 2016

Colorado Department of Public Health & Environment  
APCD-SS-B1  
4300 Cherry Creek Drive South  
Denver, Colorado 80246

**RE: Jack L. Crumley ; 2015 Annual Leak Detection and Repair (LDAR) Report**

Ladies/Gentlemen:

Jack L. Crumley is submitting the LDAR Annual Report Form as required by Colorado Regulation 7, Section XVII.F.9. In 2015, eight (8) facilities, consisting of 100% of Jack Crumley's Colorado oil and gas operations were inspected using an Approved Instrument Monitoring Method (AIMM).

Uncontrolled volatile organic compound (VOC) emissions from the condensate storage tanks for each facility are less than six tons per year (6 TPY) and were installed prior to October 15, 2014. Therefore, these facilities are subject to the one-time AIMM inspections to be completed before January 1, 2016 (Regulation 7, XVII.F.4). Monthly Audio, Visual, Olfactory (AVO) inspections were not required to begin until January 1, 2016 and are not included in the 2015 Annual LDAR Report.

Facility Name
Blake Tank Battery
Bosley Tank Battery
John. B Gebauer Tank Battery
Reed Tank Battery
Robbins Lease
Robbins Tank Battery
Snyder Tank Battery
Tuttle Walker Lease

Should you have any questions or need additional information, you may contact me at (970) 768-0993 or Lesair Environmental at (303) 904-2525.

Sincerely,



Jack L. Crumley  
Owner

Regulation 7, Section XVII.F.9

Version December 09, 2015

# Leak Detection and Repair (LDAR) Annual Report Form<sup>1</sup>



Please submit via email to: [cdphe\\_reg7LDAR\\_annualreports@state.co.us](mailto:cdphe_reg7LDAR_annualreports@state.co.us)

## Section 1: General Information

Company Name:	Jack L. Crumley		
Inspection Year:	2015	# Facilities Inspected: <sup>2</sup>	8
Contact Person:	Jack Crumley	Title:	Owner
Phone Number:	970-768-0993	E-mail Address:	jlcrcrumley@gmail.com

## Section 2: LDAR Inspections

Inspection Method	# Inspections <sup>3</sup>
AIMM at Natural Gas Compressor Stations:	0
AIMM at Well Production Facilities:	8
AVO at Well Production Facilities:	0
<b>TOTAL</b>	<b>8</b>

## Section 3: Leaking Components Details

Component Type	# Leaks Identified <sup>4</sup>	# Leaks Repaired	# Leaks on Delay of Repair List as of Dec 31
Valves:	1	1	
Connectors:	0		
Flanges:	0		
Pump Seals:	0		
Pressure Relief Devices:	0		
<b>TOTAL</b>	<b>1</b>	<b>1</b>	<b>0</b>

## Section 4: Responsible Official Certification

All information contained in the LDAR Annual Report must be certified by a responsible official as defined in Colorado Regulation No. 3, Part A, Section 1.B.38.

Please note the Colorado Statutes state that any person who knowingly, as defined in §18-1-501(6), C.R.S., makes any false material statement, representation, or certification in this document is guilty of a misdemeanor and may be punished in accordance with the provisions of §25-7 122.1, C.R.S.

I, the Responsible Official, have reviewed this annual report in its entirety and, based on information and belief formed after reasonable inquiry, I certify that the statements and information contained in this report are true, accurate and complete.

Printed/Typed Name - Responsible Official:	Title:
Jack L. Crumley	Owner
Signature:	Date:

