

Forest View Acres Water District

Operations Report – May, 2009

Prepared by Erik Tameler, Southwest Water Co.

Sampling:

The required samples were collected. Results are inside the yellow folder in the wall rack in the Arapahoe plant.

Treatment Plants:

Arapahoe Water Plant:

The plant has been operated steadily since mid April as the sole source for the district.

Transmission Line/Booster Station:

Normal Operation

Surface Water Plant:

The plant was taken off-line in mid April due to high turbidities and degradation of the collection channel.

A new production meter was ordered and picked up on May 21st. Installation will be completed within the next week or so.

The inlet channel needs to be cleaned out. There are several inches of gravel covering the inlet screen.

Distribution system:

There was a water main break on May 18th at the intersection of Pixie Park and Sandstone. A pin-hole leak was found in the white pvc pipe, and was repaired with a repair clamp. An improperly marked gas main was damaged and repaired during the excavation.

On May 7th, Southwest Water Co repaired the leak in the PRV on Red Rock Ranch Road.