

Forest View Acres Water District

Operations Report – August, 2009

Prepared by Erik Tameler, Southwest Water Co.

Sampling:

The required samples were collected for LT2ESWTR, Routine Coliform, and quarterly Disinfection Byproducts. Results are inside the yellow folder in the Arapahoe treatment plant.

Treatment Plants:

Arapahoe Water Plant:

Normal operation.

The well was pressure tested on Aug. 20th with a result of 51' of water above the pump during pumping.

Transmission Line/Booster Station:

A power supply problem was preventing the booster station from running. On Aug. 10th, Cross Diamond Electric was called to investigate. The station is now ok and operating normally.

Surface Water Plant:

On Aug. 4th, a meeting w/ R&G Engineering was held regarding SWTP improvements.

Distribution system:

A box of 12 meters was purchased from National Meter.

Two meter pit tubes sufficient to meet district depth requirements was purchased from Kepner Co. These are now available for contractor purchase.

Supplies were purchased for repairing the 1.5" poly "main" on Rockbrook Rd.

On Aug. 10th; the Nevins meter was installed.

On Aug. 11th, the leaking curb stop at 4315 Sandstone Rd was repaired.

Several Work Orders regarding meter issues were completed.