

Forest View Acres Water District

Operations Report – September, 2009

Prepared by Erik Tameler, Southwest Water Co.

Sampling:

The required samples were collected for LT2ESWTR, Routine Coliform, and Surface Water MPA. Received results are inside the yellow folder in the Arapahoe treatment plant.

Treatment Plants:

Arapahoe Water Plant:

The plant has been having some operational problems. AmWest replaced the limit switch for the booster pump and performed diagnostic evaluation of the treatment plant and well systems.

Well level testing has been performed during static and pumping phases. Results are in the logbook in the plant.

Potassium Permanganate was purchased and delivered to the plant.

Transmission Line/Booster Station:

Normal Operation.

Surface Water Plant:

Normal Operation.

Two of the primary filter Back Wash valves were rebuilt and one of the secondary filter BW valves was cleaned by DP Solutions.

Replacement placards for the new secondary filter vessels are being mailed from EPD.

Distribution system:

Several Work Orders regarding meter issues were completed.