

Forest View Acres Water District

Operations Report – October 15, 2009

Prepared by Erik Tameler, Southwest Water Co.

Sampling:

The required samples were collected for LT2ESWTR, and Routine Coliform. Received results are inside the yellow folder in the Arapahoe treatment plant.

Treatment Plants:

Arapahoe Water Plant:

The plant has been operated several times. For the short duration of these runs, the plant has operated well. However, the issues of the declining water table and the faulty check valve have been evident.

Well level testing has been performed during static and pumping phases. Results are in the logbook in the plant.

Transmission Line/Booster Station:

Normal Operation.

Surface Water Plant:

Normal Operation.

Replacement placards for the new secondary filters were received and are now in the plant.

The secondary filters were raked on 10/8. This has loosened some media that had become locked up and has improved both filter run volumes between backwashes and filter turbidities.

Distribution system:

Several Work Orders regarding meter issues were completed.