

Forest View Acres Water District

Operations Report – June, 2010

Prepared by Erik

Tameler, Southwest Water Co.

Sampling:

The required sample was collected for Routine Coliform. Received results are inside the yellow folder in the Arapahoe treatment plant.

Treatment Plants:

Arapahoe Water Plant:

Has been operating normally.

Well level readings have been taken and are on file.

Transmission Line/Booster Station:

Normal Operation.

Surface Water Plant:

Normal Operation. The plant operation and reliability has been improving. Arapahoe well is still required to offset the demand for additional water, particularly on weekends.

The dehumidifier has been purchased and will be installed before the end of the week of June 21st.

Distribution system:

No breaks or leaks reported.

Miscellaneous:

Contractors are being solicited for the booster station improvements. Proposals will be forwarded to CRS upon receipt.