

Forest View Acres Water District

Operations Report – January 2013/February 2013

Prepared by Tom Schubert

ORC Water Professionals

Arapahoe Water Plant:

- This facility remains the only potable water source supplying the District.
- The pressure ratings for the filter vessels, piping, valves, fittings and associated equipment were sent to Baseline for evaluation as requested. (see attachment)
- Parts to rebuild the Aquamatic Diaphragm Valves was received and will be installed as production run-times allows.
- The Buildings grounding wire was lose which may have caused a number of the tank radio failures or miscommunications from the telemetry. An additional two facility grounding wires were installed to prevent future interruptions.

Surface Water Plant:

- The Surface Water Plant remains off-line but does provide an opportunity to complete tasks that would cause an upset condition during normal water production.
- The monitoring equipment and associated sample supply tubing's are being meticulously cleaned and/or replaced if necessary during this temporary shut-down.
- The filter media has been disinfected in the filter vessels and are ready for startup.

Distribution System:

- Attached is the Production Report for water usages.
- The zone master meters will be removed and stored at the AWP.