

Forest View Acres Water District

Operations Report – March/April 2013
Prepared by Gabrielle Begeman
ORC Water Professionals

Arapahoe Water Plant

- This facility remains the only potable water source supplying the District.
- At the end of March, the chlorinator failed causing the plant to shut down. The autodialer was disabled for this type of shutdown. The tank ran low and eventually emptied before the problem was identified and remedied. The autodialer has been re-enabled and tested for all shut downs.
- The blow-off valve was leaking approximately 10 gpm from the well production. It had to be rebuilt.

Surface Water Plant

- The Surface Water Plant remains off-line.

Distribution System

- Attached is the Production Report for water usages.
- The new water line for 4580 Redstone Ridge Road is in the process of being installed.
- The booster pump valves were adjusted to limit water lost at the booster station.

Estimates

- We hope to have bids from the landscapers prior to the meeting.
- We hope to have an offer from the master meter company for the master meters by the meeting.
- We hope to have a bid for the tuff shed prior to the meeting.