

Forest View Acres Water District

Operations Report – April/May 2013

Prepared by Gabrielle Begeman
ORC Water Professionals

Arapahoe Water Plant

- The air compressor caused a couple of plant shut downs due to it tripping the breaker. It has sporadically done this for many months. It began to continuously trip the breaker. The air compressor was replaced in May.
- Please see the attached quote for a lean-to style Tuff Shed for storage at the AWP. The quote includes installation. Additional materials (Garden Pavers) will be purchased to level the shed site. Brenda may have another quote by the meeting.

Surface Water Plant

- The Surface Water Plant intake thawed on May 16th and the line has been flushed. The plant will be put back on-line when turbidities warrant consistent operation.
- An air relief valve was installed in the plant.
- All components were cleaned and tested prior to start-up.
- The road to the inlet has been littered with rocks from a slide over the winter. John w/ J&K will be contacted to clear. Last year we split this cost with John Cressman.

Distribution System

- Master Meter #4 was dug up and a leak was repaired.
- A Leak was fixed on Clovenhoof that sprung loose on May 12th.
- Sink-holes from previous leaks were re-graded.
- The ultrasonic master meters have been posted on the Colorado Rural Water Association web site and also Craigslist.