

Forest View Acres Water District

Operations Report –June/July 2014
Prepared by Gabrielle Begeman
ORC Water Professionals

Arapahoe Water Plant

- The plant has been running minimally.

Surface Water Plant

- The plant has been running consistently producing all of the demand of the district in the last 2 weeks.
- I should have a few quotes for replacing the roof and siding the building prior to the meeting.
- I should also have a quote for fire mitigation prior to the meeting.

Distribution System

- A Water main break occurred at 4730 Sandstone and was fixed.
- A Water main break happened at 18509 Pike View Way.
- A Water main break occurred at 4730 Red Forest Rd
- A water main break was fixed at 18650 Clovenhoof on 6/20/14
- A Leak was repaired at 3815 Sierra Vista on 7/2/14