

Forest View Acres Water District

Operations Report –October/November 2014
Prepared by Gabrielle Begeman
ORC Water Professionals

Arapahoe Water Plant

- The plant has been exercised weekly to ensure proper chemical dosage.
-

Surface Water Plant

- The plant has been running consistently producing most of the demand of the district since the previous report.
- The recycle pump system has been installed and is working well.
- The upgrades to the backwash pond are moving forward.
- Please see the attached bid for fire proofing the building. This contractor was referred to us by JDS Hydro.

Distribution System

- We had to isolate parts of the distribution system for J&K Excavation to install a new curb stop at 1 Pixie Park Drive. Upon turning the valves back on, the fire hydrant PPHY2 is inoperable. The hydrant is off at the isolation valve until the hydrant can be replaced.