

## **Forest View Acres Water District**

Operations Report –March 2015

Prepared by Gabrielle Begeman  
ORC Water Professionals

### **Arapahoe Water Plant**

- The plant has been exercised weekly.
- I am still looking into pricing on getting the new 3" service line tie in completed to enable backwashing the AWP filters with finished water.

### **Surface Water Plant**

- The plant has been producing the majority of flow demand for the month of March.
- The plant piping was broken and replaced by Glacier due to the recycle pump running against a closed valve.
- The driveway has been graded, rocked and had boulders placed to prevent accidental collisions with the new backwash pond.

### **Distribution System**

- Please see the production report for March 2015.