

Forest View Acres Water District

Operations Report – October/November 2015

Prepared by Mike Kielma and Gabrielle Begeman

ORC Water Professionals

Arapahoe Water Plant

- The plant produced water as the back-up to the surface water plant.

Surface Water Plant

- The plant is running consistently with adequate flows.
- Please see the attached quote to replace the heater as it has failed to maintain the pilot light 3x in the last month.
- The inoperable valve (B valve) was replaced on October 27th.

Distribution System

- Located main, hydrants and service lines on Lake Meadow from 1000ft. east of Oxbridge to 500 ft. west of Oxbridge. Mountain View Elec. was boring to install new conduit.
- Verified number of service taps on Forest View Rd. so that JDS could finish design of new main.
- The new meters (roughly 30) on El Rancho, Pike View and Sierra Vista have been installed and activated.
- New main was tied in on El Rancho on November 9th. Additional time to isolate, reactivate and flush lines was needed for this task.
- November 13th, the old main feeding Pike View, El Ranch and Sierra Vista was shut off permanently.
- November 14th, an emergency callout for high pressure on Rockbrook due to the new PRV needing adjustment.