



May 28, 2015

--Sent Via Email--

Colorado Department of Public Health and Environment
Air Pollution Control Division
cdphe_reg7ldar_annualreports@state.co.us
4300 Cherry Creek Drive South
Denver, CO 80246-1530

Re: Colorado Regulation 7, XVII.F.9 Annual Report for 2014

Air Pollution Control Division:

Anadarko Petroleum Corporation (APC) has prepared this submittal to satisfy the requirements of Colorado Regulation Number 7, Section XVII.F.9, which pertains to leak detection and repair (LDAR) reporting for well production facilities and natural gas compressor stations.

Pursuant to Regulation 7, this annual report is inclusive of both well production facilities and natural gas compressor stations that are owned by APC. Please note that the attached report reflects more LDAR activities than were required by Regulation 7. APC proactively started LDAR at some facilities before the requirements of Section XVII.F of Regulation 7 were applicable.

Please feel free to contact me at 720-929-6135 or Joel.Kenyon@Anadarko.com with any questions.

Thank You,
Anadarko Petroleum Corporation

A handwritten signature in black ink, appearing to read "Joel Kenyon".

Joel Kenyon
HSE Representative

Enclosure



Leak Detection and Repair (LDAR) Annual Report Form (Version December 18, 2014)

Regulation 7, Section XVII.F.9

Section 1: General Information

Company Name:	Anadarko Petroleum Corporation		
Inspection Year:	2014	# Facilities Inspected: ¹	113
Contact Person:	Joel Kenyon	Title:	HSE Representative
Phone Number:	(720) 929-6135	E-mail Address:	Joel.Kenyon@Anadarko.com

¹ Identify the list of facilities inspected in the Addendum Table 1 in Section 5

Section 2: LDAR Inspections

Inspection Method	# Inspections
AIMM at Natural Gas Compressor Stations:	20
AIMM at Well Production Facilities:	100
AVO at Well Production Facilities:	18*
TOTAL	138

* Only AVO inspections that were required under Regulation 7, Section XVII.F.9 are reflected

Section 3: Leaking Components Details

Component Type	# Leaks Identified	# Leaks Repaired	# Leaks on Delay of Repair List as of Dec 31
Valves:	21	20	1
Connectors:	14	14	0
Flanges:	3	3	0
Pump Seals:	0	0	0
Pressure Relief Devices:	27	27	0
TOTAL	65	64	1

Section 4: Responsible Official Certification

All information contained in the LDAR Annual Report must be certified by a responsible official as defined in Colorado Regulation No. 3, Part A, Section 1.B.38.

Please note the Colorado Statutes state that any person who knowingly, as defined in §18-1-501(6), C.R.S., makes any false material statement, representation, or certification in this document is guilty of a misdemeanor and may be punished in accordance with the provisions of §25-7 122.1, C.R.S.

I, the Responsible Official, have reviewed this annual report in its entirety and, based on information and belief formed after reasonable inquiry, I certify that the statements and information contained in this report are true, accurate and complete.

Printed/Typed Name - Responsible Official:	Title:
Paul Wages	Operations Manager
Signature: <i>Paul Wages</i>	Date: <i>May 28, 2015</i>
	5/28/2015