



# Leak Detection and Repair (LDAR) Annual Report Form (Version December 18, 2014)

Regulation 7, Section XVII.F.9

## Section 1: General Information

Company Name:	Augustus Energy Resources LLC		
Inspection Year:	2014	# Facilities Inspected: <sup>1</sup>	12
Contact Person:	Loni Davis	Title:	Oper. Acctg & Reg Spec
Phone Number:	970-332-3585	E-mail Address:	ldavis@augustusenergy.com

<sup>1</sup> Identify the list of facilities inspected in the Addendum Table 1 in Section 5

## Section 2: LDAR Inspections

Inspection Method	# Inspections
AIMM at Natural Gas Compressor Stations:	12
AIMM at Well Production Facilities:	
AVO at Well Production Facilities:	
<b>TOTAL</b>	<b>12</b>

## Section 3: Leaking Components Details

Component Type	# Leaks Identified	# Leaks Repaired	# Leaks on Delay of Repair List as of Dec 31
Valves:	2	2	
Connectors:	6	6	
Flanges:	7	5	
Pump Seals:	0	0	
Pressure Relief Devices:	0	0	
<b>TOTAL</b>	<b>15</b>	<b>13</b>	

## Section 4: Responsible Official Certification

All information contained in the LDAR Annual Report must be certified by a responsible official as defined in Colorado Regulation No. 3, Part A, Section 1.B.38.

Please note the Colorado Statutes state that any person who knowingly, as defined in §18-1-501(6), C.R.S., makes any false material statement, representation, or certification in this document is guilty of a misdemeanor and may be punished in accordance with the provisions of §25-7 122.1, C.R.S.

I, the Responsible Official, have reviewed this annual report in its entirety and, based on information and belief formed after reasonable inquiry, I certify that the statements and information contained in this report are true, accurate and complete.

Printed/Typed Name - Responsible Official:	Title:
Duane Zimmerman	VP - Operations
Signature:	Date:
<i>Duane Zimmerman</i>	4/17/15

