BONANZA CREEK

410 17th Street, Suite 1500
Denver, CO 80202
(720) 440-6100 phone
(720) 305-0804 fax

Bonanzacrk.com

May 15, 2015

Chris Laplante
Colorado Department of Public Health and Environment
Air Pollution Control Division
APCD-SS-B1
4300 Cherry Creek Drive South
Denver, Colorado 80246-1530

RE: Bonanza Creek Energy Operating Company, LLC
LDAR Annual Report
Regulation 7, XVII.F.9

Dear Mr. Laplante,

Bonanza Creek Energy Operating Company, LLC (BCEOC) is submitting this annual report as required under Regulation 7, XVII.F.9. Included with this letter is the requisite Annual Report Form that lists all of the LDAR inspections performed at facilities that became subject to Reg. 7 XVII.F in 2014. The leaks identified and subsequently repaired at inspected facilities during this reporting period are identified in Section 3 on the attached and as required under Section XVII.F.9.c-d.

The signed Responsible Official Certification, as required under Section XVII.F.9.f, is also included in Section 4 of the attached Annual Report Form. If you have questions or need additional information please contact me at 303-803-1724 or John Gardner at 303-803-1717.

Sincerely,

Jerry Dismukes
Senior Air Quality Specialist

Attachments: As stated

cc: File

Leak Detection and Repair (LDAR) Annual Report Form (Version December 18, 2014)

Regulation 7, Section XVII.F.9

Section 1: General Information

Company Name:	Bonanza Creek Energy Operating Company, LLC		
Inspection Year:	2014	# Facilities Inspected:[1]	7
Contact Person:	John Gardner	Title:	Sr. Environmental Specialist
Phone Number:	303-803-1717	E-mail Address:	jgardner2@bonanzacrk.com

[1] Identify the list of facilities inspected in the Addendum Table 1 in Section 5

Section 2: LDAR Inspections

Inspection Method	# Inspections
AIMM at Natural Gas Compressor Stations:	0
AIMM at Well Production Facilities:	17
AVO at Well Production Facilties:	0
TOTAL	

Section 3: Leaking Components Details

Component Type	# Leaks Identified	# Leaks Repaired	# Leaks on Delay of Repair List as of Dec 31
Valves:	5	5	0
Connectors:	25	25	0
Flanges:	1	1	0
Pump Seals:	0	0	0
Pressure Relief Devices:	1	1	0
TOTAL	32	32	0

Section 4: Responsible Official Certification

All information contained in the LDAR Annual Report must be certified by a responsible official as defined in Colorado Regulation No. 3, Part A, Section 1.B.38.

Please note the Colorado Statutes state that any person who knowingly, as defined in §18-1-501(6), C.R.S., makes any false material statement, representation, or certification in this document is guilty of a misdemeanor and may be punished in accordance with the provisions of §25-7 122.1, C.R.S.

I, the Responsible Official, have reviewed this annual report in its entirety and, based on information and belief formed after reasonable inquiry, I certify that the statements and information contained in this report are true, accurate and complete.

Printed/Typed Name - Responsible Official:	Title:
Dave Lillo	SVP, Production & Operations
Signature: Dave J. Lillo	Date: 5-14-2015

Section 5: Facilties Inspected

Addendum Table 1		
Plant AIRS ID (e.g., 123/7896)	**Location (e.g., Lat/Long)**	**Facility Name**
Per Regulation 7 XVII.F.9 facility information is not required.		
Per PS Memo 14-04 8.2 (January 22, 2015) *'No site information or AIRS ID is required as part of the annual report for any facility, regardless of size .'*		