



May 8, 2015

Mr. Christopher Laplante  
Oil and Gas Permitting Supervisor  
Colorado Department of Public Health and Environment  
Air Pollution Control Division, APCD-SS-B1  
4300 Cherry Creek Drive South  
Denver, CO 80246-1530

RE: Endeavour Operating Corporation - Wiley O 23-3-97 H1 Well Pad LDAR Report  
Kleinfelder Project No.: 20152142.001A

Dear Mr. Laplante:

On behalf of Endeavour Operating Corporation (Endeavour), we are submitting the annual Leak Detection and Repair (LDAR) report for the above referenced facility. The report uses the Colorado Department of Public Health and Environment LDAR Annual Report Form to comply with Regulation 7, Section XVII.F.9. Should pending well production data indicate a need for more frequent inspections in the 2015 calendar year according to Regulation 7, Section XVII.F.4.c, then an updated report will be submitted at the appropriate time.

If you have any questions regarding this documentation, or if additional information is required, please contact me at (303) 297-5761 or by email at [cdkeefe@kleinfelder.com](mailto:cdkeefe@kleinfelder.com).

Sincerely,

**KLEINFELDER**

A handwritten signature in cursive script that reads "Chris Keefe".

Chris Keefe  
Air Quality Scientist

cc: Mr. Graham McClave, Endeavour International Corp.

Enclosures: LDAR Annual Report



# Leak Detection and Repair (LDAR) Annual Report Form (Version December 18, 2014)

Regulation 7, Section XVII.F.9

## Section 1: General Information

Company Name:	Endeavour Operating Corporation		
Inspection Year:	2015	# Facilities Inspected: <sup>1</sup>	1
Contact Person:	Graham McClave	Title:	Geologist
Phone Number:	720-979-0706	E-mail Address:	<a href="mailto:graham.mcclave@endeavourcorp.com">graham.mcclave@endeavourcorp.com</a>

<sup>1</sup> Identify the list of facilities inspected in the Addendum Table 1 in Section 5

## Section 2: LDAR Inspections

Inspection Method	# Inspections
AIMM at Natural Gas Compressor Stations:	
AIMM at Well Production Facilities:	1
AVO at Well Production Facilities:	
<b>TOTAL</b>	<b>1</b>

## Section 3: Leaking Components Details

Component Type	# Leaks Identified	# Leaks Repaired	# Leaks on Delay of Repair List as of Dec 31
Valves:	0	0	0
Connectors:	0	0	0
Flanges:	0	0	0
Pump Seals:	0	0	0
Pressure Relief Devices:	0	0	0
<b>TOTAL</b>	<b>0</b>	<b>0</b>	<b>0</b>

## Section 4: Responsible Official Certification

All information contained in the LDAR Annual Report must be certified by a responsible official as defined in Colorado Regulation No. 3, Part A, Section 1.B.38.

Please note the Colorado Statutes state that any person who knowingly, as defined in §18-1-501(6), C.R.S., makes any false material statement, representation, or certification in this document is guilty of a misdemeanor and may be punished in accordance with the provisions of §25-7 122.1, C.R.S.

I, the Responsible Official, have reviewed this annual report in its entirety and, based on information and belief formed after reasonable inquiry, I certify that the statements and information contained in this report are true, accurate and complete.

Printed/Typed Name - Responsible Official:	Title:
Graham McClave	Geologist
Signature:	Date:
	5/7/2015

