



Leak Detection and Repair (LDAR) Annual Report Form

(Version December 18, 2014)
Regulation 7, Section XVII.F.9

Section 1: General Information

Company Name:	Synergy Resources		
Inspection Year:	2014	# Facilities Inspected: ¹	6
Contact Person:	David Pennington	Title: Prod/EHS Fore	
Phone Number:	970-230-0435	E-mail Address:	dpennington@syrginfo.com

¹ Identify the list of facilities inspected in the Addendum Table 1 in Section 5

Section 2: LDAR Inspections

Inspection Method 21	# Inspections
AIMM at Natural Gas Compressor Stations:	
AIMM at Well Production Facilities:	15
AVO at Well Production Facilities:	484
TOTAL	499

Section 3: Leaking Components Details

Component Type	# Leaks Identified	# Leaks Repaired	# Leaks on Delay of Repair List as of Dec 31
Valves:	3	3	0
Connectors:	15	15	0
Flanges:	1	1	0
Pump Seals:	0	0	0
Pressure Relief Devices:	6	6	0
TOTAL	25	25	0

Section 4: Responsible Official Certification

All information contained in the LDAR Annual Report must be certified by a responsible official as defined in Colorado Regulation No. 3, Part A, Section 1.B.38.

Please note the Colorado Statutes state that any person who knowingly, as defined in §18-1-501(6), C.R.S., makes any false material statement, representation, or certification in this document is guilty of a misdemeanor and may be punished in accordance with the provisions of §25-7 122.1, C.R.S.

I, the Responsible Official, have reviewed this annual report in its entirety and, based on information and belief formed after reasonable inquiry, I certify that the statements and information contained in this report are true, accurate and complete.

Printed/Typed Name - Responsible Official:	Title:
David Pennington	Production/ Ehs Foreman
Signature:	Date:
<i>David Pennington</i>	5/29/2015

