



May 18, 2015

Mr. Mark McMillan
Colorado Department of Public Health & Environment
Air Pollution Control Division
4300 Cherry Creek Drive South
Denver, Colorado 80246-1530

RE: Regulation 7 LDAR 2014 Annual Report

Dear Mr. McMillan,

WPX Energy Rocky Mountain, LLC (WPX Energy), is submitting an annual report for 2014 LDAR Inspections as required per Regulation Number 7, Section XVII.F.9.

If you require additional information or have any questions, please contact me at 970-263-2792, or by email at Brandon.Danforth@wpxenergy.com.

Sincerely,

WPX Energy Rocky Mountain, LLC

A handwritten signature in blue ink, appearing to read "Brandon Danforth". The signature is stylized and includes a long horizontal flourish extending to the right.

Brandon Danforth
Environmental Supervisor

Enclosures

Regulation 7 Leak Detection and Repair (LDAR) Annual Report

General Information

Company Name:	WPX Energy Rocky Mountain, LLC	Inspection Year:	2014
---------------	--------------------------------	------------------	------


LDAR Inspection Counts

# Facilities Inspected	304	# Inspections	313
------------------------	-----	---------------	-----

Component Leaks and Repairs

Component Type	# Leaks Identified	# Leaks Repaired	# Leaks on Delay of Repair List as of Dec 31
Valves:	0	0	0
Connectors:	0	0	0
Flanges:	0	0	0
Pump Seals:	0	0	0
Pressure Relief Devices:	0	0	0

Responsible Official Certification

I, the Responsible Official, have reviewed this annual report in its entirety and, based on information and belief formed after reasonable inquiry, I certify that the statements and information contained in this report are true, accurate and complete.	
Printed/Typed Name - Responsible Official:	Title:
JoDell Mizoue	Environmental Manager
Signature:	Date:
	5/18/2015